

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 10/24/2017
NMOCD Dist 2

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1718029380

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: XTO Energy	Contact Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, NM 88220	Telephone No. 575-887-7329
Facility Name: Poker Lake Unit 213 Battery	Facility Type Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-33859
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter P	Section 18	Township 24S	Range 30E	Feet from the 860	North/South Line South	Feet from the 660	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.212856 Longitude -103.913909

NATURE OF RELEASE

Type of Release: Crude oil	Volume of Release: 12.3 bbls	Volume Recovered: 10 bbls
Source of Release - Free water knockout	Date and Hour of Occurrence: 6/18/17, Unknown in a.m.	Date and Hour of Discovery: 6/18/17, 10:00 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour: N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A



Describe Cause of Problem and Remedial Action Taken.*

The skim pump was turned on, sending oil into the flow line. A valve was not shut off on the battery side, causing oil to spill onto the ground. The valve was shut in and locked.

Describe Area Affected and Cleanup Action Taken.*

Approximately 2,600 ft² inside the caliche containment was impacted. The release was fully contained within the secondary containment berm. The facility was torn down and fully remediated with contaminated soils taken to an NMOCD approved facility with soil samples being retrieved and analyzed at an NMOCD approved laboratory. Clean non-impacted imported soils were brought back in and the area was compacted and contoured to the surrounding area. A detailed report of the remediation activities has been submitted as Poker Lake Unit 213 Termination Request that is also associated with 2RP-4243.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Amy Ruth	Approved by Environmental Specialist: 		
Title: EHS Remediation Specialist	Approval Date: 11/2/17	Expiration Date: N/A	
E-mail Address: ACRuth@basspet.com xtoenergy.com	Conditions of Approval: Like Approval BLM	Attached <input type="checkbox"/>	
Date: 10-24-17 Phone: 432-661-0571	FINAL		

* Attach Additional Sheets If Necessary

2RP-4265