


Location Nash Draw 42Date 5/10/18 13Project / Client XTOEric Carroll

0800 EC on site to hydro excavate remaining soil at EX-7

0815 Blue Star on site 1 hydro vac truck
2 crew

Review JSA, Checklist

Extending NE corner of EX



Storage tanks

Remove additional 6' east to 5' sample bgs.

Sample	PID	Qtab	Time	Depth
EX-10	ND	288	1015	3'

With 60% error qtab under 600 mg/kg

1 sample collected for Xenco lab
BTEX, TPH, CI

1115 EC off site