

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OCD Rec'd: 08/16/18

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Matador Resources Company 371287	Contact John Hurt
Address 5400 LBJ Freeway, Suite 1500 Dallas, TX 75240	Telephone No. 972-371-5200
Facility Name RUSTLER BREAKS SWD #2	Facility Type Salt Water Disposal

Surface Owner Private	Mineral Owner Private	API No. 30-015-44240
-----------------------	-----------------------	----------------------

LOCATION OF RELEASE

Unit Letter D	Section 6	Township 24S	Range 28E	Feet from the 1064	North/South Line North	Feet from the 230	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.2513024 Longitude 104.1347605NAD83

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 36	Volume Recovered 0
Source of Release Equipment Failure	Date and Hour of Occurrence 7/23/18 8:00 a.m.	Date and Hour of Discovery 7/23/18 10:00p.m..
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Lucas Middleton(SMA)	Date and Hour 7/27/18	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A



Describe Cause of Problem and Remedial Action Taken.*

Equipment failed near the well head causing a release. The release occurred around the wellhead. Spread east and north of the well head within the pad. No waterways were reached.

Describe Area Affected and Cleanup Action Taken.*

The release affected the well pad only. Delineation and remediate of the site will be done as per NMOCD rules and regulations.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: John Hurt	Approved by Environmental Specialist: 	
Title: RES Specialist	Approval Date: 08/18/18	Expiration Date: N/A
E-mail Address: Jhurt@matadorresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/30/18 Phone: 972-371-5200	N/A	2RP-4926

* Attach Additional Sheets If Necessary

A#: pMAP1823044641

I#: nMAP1823045057