

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company XTO Energy	Contact Kyle Littrell
Address 3104 E Greene Street Carlsbad, N.M. 88220	Telephone No. 432-221-7331
Facility Name PLU 320 Tank Battery (2RP-2888)	Facility Type Exploration and Production
Surface Owner Federal	Mineral Owner Federal
API No. 30-015-39810	

#### LOCATION OF RELEASE



Unit Letter O	Section 4	Township 24S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude \_\_\_\_\_ N 32.243554 \_\_\_\_\_ Longitude \_\_\_\_\_ -103.886910 \_\_\_\_\_ NAD83

#### NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 20 bbls	Volume Recovered: None
Source of Release: Flare Stack	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: 3/11/15 at 2:30pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Tony Savoie	Date and Hour : 3/12/15 at 8:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Crude oil was released out of the flare stack. Cause not known at the time of discovery.		
Describe Area Affected and Cleanup Action Taken.* The release flow path and ponded areas measured approximately 3,660 sq. ft. of pasture and pipeline right-of-way's. It also misted an area of approximately 15,600 sq. ft. There are two buried pipelines under the flow path and ponded areas. The stained area was left as is pending final remediation.  The impacted soil was excavated. Confirmation soil samples were collected from the release area and excavation between June 26, 2018 and June 29, 2018. Laboratory analytical results for the confirmation soil samples indicate BTEX, TPH, and chloride concentrations are compliant with NMOCD remediation action levels. A Closure Request Report is attached describing all field activities. XTO requests no further action for this release.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

#### OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Kyle Littrell	Approval Date: 10/02/18	Expiration Date: N/A
Title: SH&E Coordinator	Conditions of Approval:	
E-mail Address: Kyle.Littrell@xtoenergy.com	Attached <input type="checkbox"/>	
Date: 9/17/2018	Phone: 432-221-7331	N/A

\* Attach Additional Sheets If Necessary

A#: pAB1507553980

I#: nAB1507554274

FINAL 2RP-2888