

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report



Name of Company XTO Energy	Contact Kyle Littrell
Address 3104 E Greene Street Carlsbad, N.M. 88220	Telephone No. 432-221-7331
Facility Name PLU 320H (2RP-3769)	Facility Type: Exploration and Production
Surface Owner Federal	Mineral Owner Federal
API No. 30-015-39810	

LOCATION OF RELEASE

Unit Letter N	Section 4	Township 24S	Range 30E	Feet from the 2590	North/South Line South	Feet from the 1670	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.242954 Longitude -103.885796 NAD83

NATURE OF RELEASE

Type of Release: Crude Oil and Produced Water	Volume of Release: 111 bbls oil and 35 bbls produced water	Volume Recovered: 80 bbls oil and 15 bbls of produced water
Source of Release: Heater-Treater Gasket	Date and Hour of Occurrence: 7-6-16 @ 11:30 am	Date and Hour of Discovery: 7-6-16 @ 8:45 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson and Jim Amos	
By Whom? Bradley Blevins	Date and Hour: 7-6-16 @ 11:13 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* BOPCO EHS was notified of a release that occurred when the gasket failed on the production heater treater. The majority of the fluid was contained within an earth berm with the exception of a light spray to the location. A vacuum truck was called to the location to recover the standing fluid. A response crew was sent to the location to conduct an initial scrape of the well pad.		
Describe Area Affected and Cleanup Action Taken.* The majority of the affected area was within the earth berm that surrounds the production equipment; the standing fluid was recovered by a vacuum truck. A light spray to the location was observed; an initial response crew conducted a scrape of the well pad. The impacted soil was excavated. Confirmation soil samples were collected from the release area and excavation between March 6, 2018 and June 26, 2018. Laboratory analytical results for the confirmation soil samples indicate BTEX, TPH, and chloride concentrations are compliant with NMOCD remediation action levels, except in eastern excavation sidewall where impacted soil within close proximity to the active process equipment was left in-place per XTO's safety policy. The remaining impacted will be excavated when the site is closed or reconfigured to allow for remediation to be completed. A Closure Request Report is attached describing all field activities. XTO requests no further action for this release.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kyle Littrell	Approved by Environmental Specialist: 	
Title: SH&E Coordinator	Approval Date: 10/02/18	Expiration Date: N/A
E-mail Address: Kyle.Littrell@xtoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9/17/2018	Phone: 432-221-7331	N/A