

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico NM Oil Conservation Div.
Energy Minerals and Natural Dist. II - Artesia
Resources Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Received Submit to appropriate OCD District office
11/02/18

Incident ID	NAB1831038467
District RP	2RP-5037
Facility ID	
Application ID	pAB1831037847

Release Notification

Responsible Party

Responsible Party	Oxy USA Inc.	OGRID	16696
Contact Name	Wade Dittrich	Contact Telephone	(575) 390-2828
Contact email	Wade_Dittrich@oxy.com	Incident # (assigned by OCD)	NAB1831038467
Contact mailing address	PO Box 4294; Houston, TX 77210		

Location of Release Source

Latitude 32.21560 Longitude -103.97514
(NAD 83 in decimal degrees to 5 decimal places)

Site Name	Cedar Canyon 15-1 WTF South	Site Type	Water Transfer Facility
Date Release Discovered	8/15/2018	API# (if applicable)	30-015-42797

Unit Letter	Section	Township	Range	County
K	15	24S	29E	EDDY

Surface Owner: ☐ State ☐ Federal ☐ Tribal ☒ Private (Name: BRANTLEY, JOHN & MCDONALD, HENRY)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) <u>25</u>	Volume Recovered (bbls) <u>20</u>
	Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

TRANSFER PUMP SEAL CAUSED LEAK BETWEEN NORTH AST CLUSTER

State of New Mexico
Oil Conservation Division

Incident ID	NAB1831038467
District RP	2RP-5037
Facility ID	
Application ID	pAB1831037847

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? THE RELEASE WAS GREATER THAN 25 BBLS
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? YES, BY WADE DITTRICH VIA EMAIL ON 8/17/2018 @9:46 AM TO MIKE BRATCHER, MARIA PRUETT-NMOCD	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

- ☒ The source of the release has been stopped.
- ☒ The impacted area has been secured to protect human health and the environment.
- ☒ Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.
- ☒ All free liquids and recoverable materials have been removed and managed appropriately.


If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Wade Dittrich

Title: Environmental Specialist

Signature: 

Date: 11-2-18

email: wade_dittrich@oxy.com

Telephone: (575) 390-2828

OCD Only

Received by:  Date: 11/06/2018