

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NAB1833044068
District RP	2RP-5066
Facility ID	
Application ID	pAB1833043665

Release Notification

Responsible Party

Responsible Party EOG Y Resources, Inc.	OGRID 25575
Contact Name Robert Asher	Contact Telephone 575-748-4217
Contact email bob_asher@eogresources.com	Incident # (assigned by OCD) NAB1833044068
Contact mailing address 104 S. 4 th Street, Artesia, NM 88210	

Location of Release Source

Latitude 32.54242 Longitude -104.28284
(NAD 83 in decimal degrees to 5 decimal places)

Site Name Leontodon ASH Federal Com #1	Site Type Facility
Date Release Discovered 11/7/2018	API# 30-005-63324

Unit Letter	Section	Township	Range	County
O	10	9S	26E	Chaves

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

☐ Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
☒ Produced Water	Volume Released (bbls) 7	Volume Recovered (bbls) 2
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	☒ Yes ☐ No
☐ Condensate	Volume Released (bbls)	Volume Recovered (bbls)
☐ Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
☐ Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release:
Transfer pump seal failed.

State of New Mexico
Oil Conservation Division

Incident ID	NAB1833044068
District RP	2RP-5066
Facility ID	
Application ID	pAB1833043665

Was this a major release as defined by 19.15.29.7(A) NMAC?

☐ Yes ☒ No

If YES, for what reason(s) does the responsible party consider this a major release?

If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

- ☒ The source of the release has been stopped.
- ☒ The impacted area has been secured to protect human health and the environment.
- ☒ Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.
- ☒ All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Robert Asher

Title: Environmental Supervisor

Signature: 

Date: _____

email: bob_asher@eogresources.com

Telephone: 575-748-4217

OCD Only

Received by: 

Date: 11/26/2018

Well Reports

CHART						CHART					
ST.	DIF.	TURNS PER MIN.	CHART SETTING	WELL HEAD SET	GALVE	BBL	ST.	DIF.	TURNS PER MIN.	CHART SETTING	BBL
120	0	120	0				107	0	120	0	120
-	-	-	0				114	0	120	0	120
-	-	-	0				109	0	120	0	120
-	-	-	0				108	0	120	0	120
120	0	120	0				108	0	120	0	120
-	-	-	0				110	0	120	0	120
-	-	-	0				110	0	120	0	120
-	-	-	0				112	0	120	0	120
-	-	-	0				112	0	120	0	120
-	-	-	0				112	1	120	0	120
-	-	-	0				112	1	120	0	120
-	-	-	0				156	1	120	0	120
-	-	-	0				155	1	120	0	120
120	0	120	0				104	1	120	0	120
100	25	100	1				106	1	120	0	120
-	-	-	0				108	1	120	0	120
-	-	-	0				110	1	120	0	120
-	-	-	0				134	1	120	0	120
140	0	140	0				105	1	120	0	120
							114	1	120	0	120

Dandelion "AFW" Fed Com # 1

2 X 25 = 38

Leontodon "ASH" Fed # 1

2 X 5 = 151
15207

**Forrest Welding
Roustabout Service**

P.O. Box 1735
Roswell, New Mexico 88202-1735
575) 622-4350
NM Lic. 030799

Invoice No. 10098

Date: 11-8-2010

Customer: EOG Resources Inc.
Artesia Site

Job Location: Leonard Ash Fed #1

Description

Recover 100 gallons of water in berm. Clean out meter.

Water trailer. \$300.00

\$ 300.00

Keith Hutchens

#9118

810-006

Prop # 106023

2% discount if paid within 10 days.

Subtotal \$300.00

Tax \$19.56

Total \$319.56