

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

nAB1823342523

Release Notification and Corrective Action

pAB1823342292

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company OXY USA WTP LP 192463	Contact JESSICA LOPEZ	
Address PO BOX 4294; HOUSTON, TX 77210	Telephone No. 432-685-5777	
Facility Name PIGLET 21 STATE #1 CTB	Facility Type BATTERY	
Surface Owner STATE	Mineral Owner STATE	API No. 30-015-39371

LOCATION OF RELEASE



Unit Letter I	Section 21	Township 17S	Range 28E	Feet from the 1627	North/South Line SOUTH	Feet from the 345	East/West Line EAST	County EDDY
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	-------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release GAS-FLARE	Volume of Release 16897 MCF	Volume Recovered 0
Source of Release GAS- FLARE	Date and Hour of Occurrence BEGIN 8/7/2018 END 11/5/2018	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* FLARE WAS DUE TO DCP BOOTLEG SATION WAS DOWN.		
Describe Area Affected and Cleanup Action Taken.*		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: JESSICA LOPEZ	Approved by Environmental Specialist: 	
Title: ENVIRONMENTAL TECH	Approval Date: 3/01/2019	Expiration Date: N/A
E-mail Address: JESSICA_LOPEZ@OXY.COM	Conditions of Approval:	Attached <input type="checkbox"/> 2RP-4943
Date: 2/25/19	Phone: 432-238-3997	

* Attach Additional Sheets If Necessary