

Location:	Big Eddy Unit DI4B #247H (30-015-43647)	
Spill Date:	7/27/2019	
Approximate Area=	4,495.00	ft ²
Average Saturation (or depth) of Spill=	2.00	inches

Average Porosity Factor=	0.03	
Approximate Volume Recovered=	1	bbls

VOLUME OF LEAK		
Total Treated Water=	5.00	barrels

VOLUME RECOVERED		
Total Treated Water=	1	barrels