

| | | |
|--------------------|--|--|
| Location: | Remuda Frac Recycle Pond (30-015-30794 Remuda Basin St 10) | |
| Spill Date: | 8/21/2019 | |

| | | |
|--|----------|-----------------|
| | | |
| Approximate Area 1= | 7,426.00 | ft ² |
| Average Saturation (or depth) of Spill= | 6.00 | inches |

| | | |
|--------------------------------------|------|------|
| Average Porosity Factor= | 0.15 | |
| Approximate Volume Recovered= | 0 | bbls |

| | | |
|------------------------------|-------|---------|
| VOLUME OF LEAK | | |
| Total Produced Water= | 99.19 | barrels |

| | | |
|--|----------|-----------------|
| Approximate Area 2= | 8,607.00 | ft ² |
| Average Saturation (or depth) of Spill= | 10.00 | inches |

| | | |
|--------------------------------------|------|------|
| Average Porosity Factor= | 0.20 | |
| Approximate Volume Recovered= | 0 | bbls |

| | | |
|------------------------------|--------|---------|
| VOLUME OF LEAK | | |
| Total Produced Water= | 255.48 | barrels |