

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Incident ID	<b>NVV2003555031</b>
District RP	
Facility ID	
Application ID	

## Release Notification

### Responsible Party

Responsible Party: Chevron USA, Inc.	OGRID: 4323
Contact Name: Josepha DeLeon	Contact Telephone: 432-425-1528
Contact email: jdx@chevron.com	Incident # (assigned by OCD) <b>NVV2003555031</b>
Contact mailing address: 1616 E. Bender Blvd., Hobbs, NM 88240	

### Location of Release Source

**Latitude 32.032810 Longitude -103.612884**

(NAD 83 in decimal degrees to 5 decimal places)

Site Name: Salado Draw Pad 10	Site Type: Drill Site
Date Release Discovered: 10/23/2019	API# (if applicable): 30-025-44485, 30-025-44487, 30-025-44486, 30-025-44488

Unit Letter	Section	Township	Range	County
C	19	26S	33E	<del>Eddy</del> <b>Lea</b> <del>VV</del>

Surface Owner:  State  Federal  Tribal  Private (Name: \_\_\_\_\_)

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls): 19.44 barrels	Volume Recovered (bbls): 0 barrels
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units):	Volume/Weight Recovered (provide units)

Cause of Release:

Spool nipple threads corroded and failed and broke off resulting in spill to land of 19 barrels produced water. No recovery of liquid.

Form C-141

State of New Mexico  
Oil Conservation Division

Page 2

Incident ID	NVV2003555031
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?  <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Jim Griswold, voicemail 10/24/2019 as initially estimated volume would exceed 25 barrels.	

### Initial Response

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Signature: 	Date: November 4, 2019
Printed Name: Josepha DeLeon	Title: Environmental Compliance Specialist
email: <a href="mailto:jdx@chevron.com">jdx@chevron.com</a>	Telephone: 432-425-1528
<b><u>OCD Only</u></b>	
Received by: <u>Victoria Venegas</u>	Date: <u>02/04/2020</u>

Form C-141

State of New Mexico  
Oil Conservation Division

Page 3

Incident ID	
District RP	
Facility ID	
Application ID	

### Fluid in Soil Spill

All dimensions in feet !					
Shape	Area #	length/diameter	width	Depth-Soil Penetration	Total Volume of Fluid in Soil Pore Space (15%) in barrels
circle	1	61		0.0833	6.50
triangle	2	105	4	0.0833	0.47
rectangle	3	158	4	0.0833	1.41
rectangle	4	415	5	0.0833	4.62
circle	5	28		0.0833	1.37
rectangle	6	232	3	0.0833	1.55
rectangle	7	232	1	0.0833	0.52
rectangle	8	221	1	0.0833	0.49
rectangle	9	39	29	0.0833	2.52
					19.44

Form C-141

State of New Mexico  
Oil Conservation Division

Page 4

Incident ID	
District RP	
Facility ID	
Application ID	



Form C-141

State of New Mexico  
Oil Conservation Division

Page 5

Incident ID	
District RP	
Facility ID	
Application ID	

