
Liner Integrity Inspection (Photos Attached)

Company Representative(s) Medpart Samjani	· sometwalk in containment from la	Liner remains intact Liner had the ability to contain the leak in question:	Responsible party has visually inspected the liner	Date: 3/4/2020 Facility: Madera 19 Federal Com 26 35 19 14/24/54/1
	large rain event 3/3 \$3/4	N (A)	Q_N	19 14/24/84/64 CTB

Liner Inspection - Madera 19 Federal Com 26 35 19 #1H, 2H, 5H, 6H CTB



Liner Inspection - Madera 19 Federal Com 26 35 19 #1H, 2H, 5H, 6H CTB





Liner Inspection - Madera 19 Federal Com 26 35 19 #1H, 2H, 5H, 6H CTB



