

Thanks,

Cory Smith
Environmental Specialist
Oil Conservation Division
Energy, Minerals, & Natural Resources
1000 Rio Brazos, Aztec, NM 87410
(505)334-6178 ext 115
cory.smith@state.nm.us

From: DeAnn Grant <agrant@concho.com>
Sent: Wednesday, February 27, 2019 1:24 PM
To: EMNRD-OCD-District1spills <EMNRD-OCD-District1spills@state.nm.us>; Mann, Ryan <rmann@slo.state.nm.us>
Cc: Griswold, Jim, EMNRD <Jim.Griswold@state.nm.us>; Jennifer Knowlton <jknowlton@concho.com>; Ike Tavarez <itavarez@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; Rebecca Haskell <RHaskell@concho.com>; DeAnn Grant <agrant@concho.com>
Subject: [EXT] (C-141 Final) Lychee BWS State Com #001H (30-025-42445) 1-25-2019

To Whom It May Concern,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.