

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

REC'D 2/3/10
VIA EMAIL (mbs)

30-015-31376

Release Notification and Corrective Action

AKW 1108946072

4/7/79

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	CHESAPEAKE OPERATING, INC.	Contact	BRADLEY BLEVINS
Address	P. O. BOX 190 HOBBS, NM 88241	Telephone No.	575-391-1462
Facility Name	Baish Federal No. 12	Facility Type	Oil Well

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE API #30-015-31376

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	9	18S	31E	990	NORTH	1650	WEST	EDDY

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	40 BBLS	Volume Recovered	25 BBLS
Source of Release	Flow line ruptured	07/16/09 9:30 A.M.	07/16/09 10:00 A.M.		
		Date and Hour of Occurrence	Date and Hour of Discovery		
Was Immediate Notice Given?		If YES, To Whom?			
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required		Mike Bratcher			
By Whom?		Date and Hour			
Cliff Brunson-BBC International, Inc.		07/17/09 9:00 AM			
Was a Watercourse Reached?		If YES, Volume Impacting the Watercourse.			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A plastic flow line ruptured releasing produced water. Vacuum trucks were used to recover free fluid. A backhoe was used to scrape wet soil to aid in the cleanup.

Describe Area Affected and Cleanup Action Taken.*

25 BBLS of fluid was recovered. Soil removal will be done and remedial actions and test results will be furnished with the final C-141.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Bradley Blevins</u>	OIL CONSERVATION DIVISION	
Printed Name: BRADLEY BLEVINS	Signed By: <u>Mike Bratcher</u>	
Title: EHS Specialist	Approved by District Supervisor	
E-mail Address: bradley.blevins@chk.com	Approval Date: <u>3/30/11</u>	Expiration Date:
Date: 07/22/09 Phone: 575-391-1462	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

4/30/11

2RP 670