

State of New Mexico
 Energy Minerals and Natural Resources
 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources
 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-141
 Revised October 10, 2003

Submit 2 Copies to appropriate
 District Office in accordance
 with Rule 116 on back
 side of form

30-015-26001

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	MERIT ENERGY	Contact	CHARIS FLORES
Address	1000 Rio Arizos Road, Aztec, NM 87410	Telephone No.	505 920 5386
Facility Name	WEST 8 24 BATTERY	Facility Type	PRODUCTION BATTERY
Surface Owner	FEDERAL	Mineral Owner	FEDERAL
		Lease No.	029422-B

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	10	175	81E	2625	ESE	2625	FUEL	EDDY
Latitude		Longitude						

NATURE OF RELEASE

Type of Release	OIL & WATER	Volume of Release	250	Volume Recovered	100
Source of Release		Date and Hour of Occurrence		Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		MIKE STURBLEFIELD			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Date and Hour: 4/15/04 9:30 AM			
		If YES, Volume Impacting the Watercourse:			
		NO			

If a Watercourse was Impacted, Describe Fully: *

N/A

Describe Cause of Problem and Remedial Action Taken: *


LINE ON PRODUCTION HEADER BLEW OUT / SHUT IN LINES

Describe Area Affected and Cleanup Action Taken: *

PICK UP EXCESS FLUID REPAIR LINE

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by District Supervisor:	
Printed Name: CHARIS FLORES	Approval Date:	Expiration Date:
Title: LEASE RUMPER	Conditions of Approval:	
E-mail Address: N/A	Attached <input type="checkbox"/>	
Date: 4/15/04	Phone: 920 5386	

Attach Additional Sheets If Necessary