

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-00858

n M4B049542560

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company BP America Production Co.	Contact Jon Lowe
P.O. Box 1089, Eunice, NM 88231	Telephone No. 505.677.3642
Facility Name Empire Abo Unit M-9	Facility Type Satellite Location

Surface Owner Federal	Mineral Owner	Lease No.
-----------------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	10	18S	27E	660	N	660	W	LEA Eddy

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 50.7 BW	Volume Recovered 45 BW
Source of Release Fiberglass fitting	Date and Hour of Occurrence 06.16.04 1:30 PM	Date and Hour of Discovery Same
Was Immediate Notice Given? X <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Stubblefield Voicemail	
By Whom? Kellie D. Murrish	Date and Hour 06.16.04 3:30 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes X <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NA

RECEIVED

JUN 21 2004

OED-ARTESIA


Describe Cause of Problem and Remedial Action Taken.*

A 3" fiberglass nipple came out of a 3" fiberglass 90. The separation of the two pieces were due to the glue weld being weak and allowing the joint to separate. The current fiberglass line will be removed and a new 3" polyline will be installed.

Describe Area Affected and Cleanup Action Taken.*

Produced water was picked up by a vacuum truck. . The spill occurred on a caliche pad with a small volume running off of the satellite location. Clean caliche was spread to dry the spilled area. Remediated on site.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kellie D. Murrish	Approved by District Supervisor:	
Title: Staff Support	Approval Date:	Expiration Date:
Date: 06.18.04 Phone: 505.394.1649	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

X FAXED to Coordinator



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

July 20, 2004

BP America Production Co.

Attn: Jon Lowe

PO Box 1089

Eunice NM 88231

Re: Empire Abo Unit # M-9

D-10-18s-27e

API: 30-015-00858

Dear Operator,

The Artesia Oil Conservation Division is in receipt of the initial Form C-141 (copy included) dated 6/18/2004 from BP America Production Co.

Please submit a Corrective Action Work Plan to the Artesia O.C.D. for correction/remediation of this release. Please use the "Guidelines For Remediation of Leaks, Spills, and Releases as your guide.

A copy of the Guidelines for Remediation of Leaks, Spills, and Releases, published 1993, can be found at the O.C.D. web address WWW.EMNRD.STATE.NM.US/OCD.

The published document can be found on the O.C.D. web page under Publications/Environmental Handbook/Miscellaneous Guidelines/Spill Prevention Clean up.

The work plan presented to the O.C.D. must include general site characteristics, soil remediation action levels, soil remediation methods, and planned analytical testing for TPH, B-TEX and Chlorides if applicable.

A final Form C-141 is required for closure of the event or release and must include a report of remediation actions taken with final analytical results attached.

Please have the requested work plan in the Artesia office on or before August 20, 2004.

The Artesia O.C.D. must be notified 24 hours prior to any remediation actions and/or subsequent soil samples taken for analysis.

In the event that a satisfactory response is not received to this letter further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe. Such a hearing may result in imposition of **CIVIL PENALTIES** for your violation of OCD rules.

If I can be of assistance in this matter please do not hesitate to contact me at 505-748-1283

Or E-mail me at mbratcher@state.nm.us.

Sincerely,

Mike Bratcher

Compliance Officer.

N.M.O.C.D.