

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Lori Wrotenbery

Director

Oil Conservation Division

10 April 2003

Murchisn Oil and Gas 1100 Mira Vista Blvd. Plano, Texas 75093-4698

Cannot be approved until an NMOCD representative has made an inspection of the location and the cleared to comply with OCD rules and regulations. Please check each item in the space provide indicate that the work has been accomplished and the location is ready for final inspection.	ound it to
1. All pits have been filled and leveled.	
2. Rat hole and cellar have been filled and leveled.	
3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set concrete to mark the exact location of the plugged well. (Marker must have operator name, lease well number and location including quarter/quarter section or unit letter, section, township, range well ID number permanently welded, stamped or otherwise engraved into the metal marker.)	name,
4. The location has been leveled as nearly as possible to original top ground contour and has cleared of all junk and equipment.	been
5. The dead men and tie downs have been cut and removed.	ter
6. If a one well lease or last remaining well on lease, the battery and burn pit locations have be leveled and cleared of all junk & equipment.	een
7. All environmental concerns have been addressed as per OCD guidelines.	
The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.	or
When all of the work outlined above has been done, please notify this office by completing, signing returning this letter to us so that our representative will not have to make more than one trip to the	ng and location.
I certify that the above work has been done and the above-mentioned lease is ready for OCD inspapproval.	ection and
Name Van Barton Field Rep. II	
Title	