

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Yates Petroleum Corp.	Contact Dan Dolan
Address 105 S 4 th St., Artesia NM 88210	Telephone No. 748-4181
Facility Name Mimosa Fed 3-Y	Facility Type SWD

Surface Owner Fed	Mineral Owner Fed	Lease No.
-------------------	-------------------	-----------

LOCATION OF RELEASE

Unit Letter <i>P</i>	Section 4	Township 20S	Range 24E	Feet from the	North/South line	Feet from the	East/West Line	County Eddy
-------------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 1000 BW	Volume Recovered 515 BW
Source of Release Power Failure	Date and Hour of Occurrence 11-07-04	Date and Hour of Discovery 1400hrs, 11-07-04
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Artesia OCD, Becky Hunt, BLM	
By Whom? Dan Dolan	Date and Hour 0800 11-08-04	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse. 10bbl Water	

If a Watercourse was Impacted, Describe Fully.*

Water run down road and continued down hill to a draw.


Describe Cause of Problem and Remedial Action Taken.*

Power Failure caused the tanks to overflow, and caused the berm to break.

Describe Area Affected and Cleanup Action Taken.*

Test of the water showed it to be under the limit for the OCD, the water carried a small amount of iron sulfide into the draw, and was Micro-Blazed to eliminate and possible THP, the Ranking is as follows, Depth to ground water-0, Wellhead protection area-0, distance to surface water body -10

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD's acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Daniel W. Dolan CWC	Approved by District Supervisor:	
Title: Environmental Regulatory Agent	Approval Date:	Expiration Date:
E-mail Address: ddolan@ypcmm.com	Conditions of Approval:	
Date: 11-12-04 Phone: 748-4181	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

FAYED