

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

FEB 04 2005

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-02078

Release Notification and Corrective Action

7 MLB0504031814

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company <b>SMITH &amp; MARRS, INC.</b>	Contact <b>Dalton Bell</b>
Address <b>811 Bullock Artesia NM 88210</b>	Telephone No. <b>505-748-2134</b>
Facility Name <b>Twin Lakes # 13</b>	Facility Type <b>Water Line</b>

Surface Owner <b>State</b>	Mineral Owner <b>State</b>	Lease No. <b>B-647</b>
-------------------------------	-------------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter <b>K</b>	Section <b>28</b>	Township <b>18S</b>	Range <b>28E</b>	Feet from the <b>1330</b>	North/South Line <b>S</b>	Feet from the <b>2310</b>	East/West Line <b>W</b>	County <b>Eddy</b>
-------------------------	----------------------	------------------------	---------------------	------------------------------	------------------------------	------------------------------	----------------------------	-----------------------

NATURE OF RELEASE

Type of Release <b>Produced Water</b>	Volume of Release <b>20 Bbls.</b>	Volume Recovered <b>20 Bbls.</b>
Source of Release <b>Water Line Leak</b>	Date and Hour of Occurrence	Date and Hour of Discovery <b>2-3-AM</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

Repaired line and picked up as much water as possible  
with vacuum truck.

Describe Area Affected and Cleanup Action Taken.\*

Lake bed which is ordinarily dry , but had some rain water  
in it at the time.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Dalton Bell</b>	Approved by District Supervisor:	<b>Accepted for record - NMOCD</b>
Title: <b>Agent</b>	Approval Date:	Expiration Date:
Date: <b>2-4-05</b> Phone: <b>748-2134</b>	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

F  
I