District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 For drilling and production facilities, submit to appropriate NMOCD District Office.
For downstream facilities, submit to Santa Fe office

Form C-144

March 12, 2004

Pit or Below-Grade Tank Registration or Closure

Is pit or below-grade tand Type of action: Registration of a pit o	k covered by a "general plan"? Yes Nor below-grade tank Closure of a pit or below-g	Io ⊠ grade tank □	
Operator: Occidental U.S.A. W.T.P. LP Telephone: 432.685.5719	334 0 U/L or Qtr/Qtr_NESE Sec _23_	 T_17SR_27E_	
Pit Type: Drilling Production Disposal Workover Emergency Lined Unlined Liner type: Synthetic Thickness 12_mil Clay Volume 11,000bbl	Below-grade tank Volume:bbl Type of fluid: Construction material: Double-walled, with leak detection? Yes If not, explain why not.		
Depth to ground water (vertical distance from bottom of pit to seasonal high water elevation of ground water.)	Less than 50 feet 50 feet or more, but less than 100 feet 100 feet or more	(20 points) 20 (10 points) (0 points)	RECEIVED
Wellhead protection area: (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.)	Yes No	(20 points) (0 points) 0	JAN 2 6 2005 UUU:ARTES
Distance to surface water: (horizontal distance to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet 200 feet or more, but less than 1000 feet 1000 feet or more	(20 points) (10 points) (0 points) 0	
	Ranking Score (Total Points)	20	
If this is a pit closure: (1) attach a diagram of the facility showing the pit's onsite offsite If offsite, name of facility date. (4) Groundwater encountered: No Yes If yes, show depth belo diagram of sample locations and excavations.	. (3) Attach a general description of remedial a sw ground surfaceft. and attach same	ction taken including reme aple results. (5) Attach soi	l sample results and a
	general permit , or an (attached) alternative Signature As operator of its responsibility for compliance corrections of the control of the	ne above-described pit of OCD-approved plan a condition of appostruction water is vater seeps in pits astruction the OCDNTACTED IMP	proval, if during encountered or after D MUST BE