

District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-34906

Release Notification and Corrective Action

NMLB 11167 55122

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company-Cimarex Energy	162683	Contact- James Tinney
Address-600 N Marienfeld Ste 600, Midland Tx 79701		Telephone No. 575 706 0095
Facility Name-Bear Bryant 31 fed com 1		Facility Type- Tank battery

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter K	Section 31	Township 14S 16S	Range 29 E	Feet from the 1850	North/South Line FSL	Feet from the 990	East/West Line FWL	County - Eddy
------------------	---------------	------------------------	---------------	-----------------------	-------------------------	----------------------	-----------------------	---------------

Latitude- 32.87556 Longitude- 104.11826

NATURE OF RELEASE

Type of Release- crude oil	Volume of Release-240bbls Done 5/30/2011	Volume Recovered-220 bbls
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos 10:00 am 5-31-11 Mike Bratcher 10:30 am 5-31-11	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Take  
Small hole in oil tank below circulating line above weld seem from internal corrosion

Describe Area Affected and Cleanup Action Take  
All oil was contained inside berm. Berm is lined with plastic, had vac truck pick up oil and move to next oil tank

RECEIVED

JUN 10 2011

NMOCD ARTESIA

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>James Tinney</i>	OIL CONSERVATION DIVISION	
Printed Name: James Tinney	Signed By: <i>Mike Bratcher</i> Approved by District Supervisor:-	
Title: Assistant Production Foreman	Approval Date: 6/16/2011	Expiration Date:
E-mail Address: jtinney@cimarex.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3-13-11 Phone: 575-706-0095	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 7/16/2011	

\* Attach Additional Sheets If Necessary

2RP-797