

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	Contact Robert Asher
Address 104 S. 4 th Street	Telephone No. 575-748-1471
Facility Name Jacque AQJ State #2	Facility Type Well Pad

Surface Owner State	Mineral Owner State	API No. 30-015-30636
------------------------	------------------------	-------------------------

LOCATION OF RELEASE

Unit Letter L	Section 34	Township 21S	Range 31E	Feet from the 1650	North/South Line South	Feet from the 330	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.43209 Longitude 103.77274

NATURE OF RELEASE

Type of Release Crude Oil & Produced Water	Volume of Release 2 B/O & 8 B/PW	Volume Recovered 0 B/O & 0 B/PW
Source of Release Poly flow line	Date and Hour of Occurrence 7/18/2014; PM	Date and Hour of Discovery 7/18/2014; PM
Was Immediate Notice Given? ☒ Yes ☐ No ☐ Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

There was a leak in the flow line, causing the release. Well was shut off; called vacuum truck and crew to repair line.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 15 X 15' was off of the well pad. Poly line was repaired and backhoe and roustabout crews were called to remove impacted soils, those soils were taken to an NMOCD approved facility. **Depth to Ground Water: >100' (approximately 175', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 0. Based on minor amounts released, site ranking of zero and impacted soils excavated/hailed, Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Robert Asher	Approved by Environmental Specialist:	
Title: NM Environmental Regulatory Supervisor	Approval Date: <u>7/29/14</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>boba@yatespetroleum.com</u>	Conditions of Approval:	Attached ☐
Date: <u>July 24, 2014</u> Phone: <u>575-748-4217</u>	2RP- <u>2401</u> Final	

* Attach Additional Sheets If Necessary