

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

Initial Report  Final Report

Name of Company Apache Corporation	Contact Bruce Baker
Address 2350 W Marland Street, Hobbs, NM 88240	Telephone No. (432) 631-6982
Facility Name Tony Federal #29	Facility Type Oil Well
Surface Owner Federal	Mineral Owner
API No. 30-015-32463	

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	19	17S	31E					Eddy

Latitude 32 49'28.693" Longitude 103 54'24.98"

#### NATURE OF RELEASE

Type of Release Oil	Volume of Release 15 barrels of oil	Volume Recovered 1 barrel of oil
Source of Release Flow line	Date and Hour of Occurrence 6/4/2014	Date and Hour of Discovery 6/4/2014
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeffery Robertson (BLM)	
By Whom? Bruce Baker	Date and Hour 6/4/2014 at 3:30 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A 3 inch poly flow line ruptured. The well was shut in and the flow line was repaired. A vacuum truck was dispatched to pick up the standing fluid.

Describe Area Affected and Cleanup Action Taken.\*

An overspray of 15,873 square feet of pasture land was affected. The area was GPS mapped, and based on a recommendation from BLM, the vegetation was washed twice with Dawn dish soap. The vegetation at the site will be monitored over time to confirm that it has remained at normal vegetative capacity.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Bruce Baker	Approved by Environmental Specialist:	
Title: Environmental Technician	Approval Date: 10/27/2014	Expiration Date: NA
E-mail Address: larry.baker@apachecorp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10-24-14 Phone: (432) 631-6982	To be further monitored to confirm revegetation.	

\* Attach Additional Sheets If Necessary

2RP-2351