

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JUL 15 2011

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NMLB 1122232511

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229/37	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Jenkins B Federal #10	Facility Type	Well location
Surface Owner	Federal	Mineral Owner	
		Lease No. (API#)	30-015-30668

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	20	17S	30E					Eddy

Latitude 32 49.496 Longitude 103 59.714

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	10bbls	Volume Recovered	5bbls
Source of Release	Injection well hose	Date and Hour of Occurrence	06/30/2011	Date and Hour of Discovery	06/30/2011 10:15 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The hose connected to the Jenkins Federal #10 Injection Well ruptured, causing the release. The well has been shut in and the hose has been replaced.

Describe Area Affected and Cleanup Action Taken.*

Initially 10bbls were released from the ruptured injection hose and we were able to recover 5bbls with a vacuum truck. The spill area measured 20' x 30' in the pasture adjacent to the Jenkins B Federal #10 location. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD / BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Signed By

Printed Name:

Josh Russo

Approved by District Supervisor:

Title:

HSE Coordinator

Approval Date:

AUG 10 2011

Expiration Date:

E-mail Address:

jrusso@conchoresources.com

Conditions of Approval:

Attached ☐

Date: 07/05/2011

Phone: 432-212-2399

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:
9/10/2011

2RP-819

* Attach Additional Sheets If Necessary