

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 3/13/2015
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077	
Facility Name: McIntyre B #7	Facility Type: Well	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-31561

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	20	17S	30E	660'	South	660'	West	Eddy

Latitude 32.8137724103499 Longitude -104.001670530599

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 5 bbls Oil ; 10 bbls PW	Volume Recovered: 3 bbls Oil ; 8 bbls PW
Source of Release: Flowline	Date and Hour of Occurrence: 9/15/2014 1:00 pm	Date and Hour of Discovery: 9/15/2014 1:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

The release was caused by corroded flowline. Repairs were made to the line and a vacuum truck was dispatched to pick up all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

The impacted area occurred at the NE corner of the location and ran into the pasture. The area was treated with microblaze. Concho had the spill site sampled to delineate any possible contamination from the release and presented a remediation work plan to the NMOCD and the BLM for approval prior to any significant remediation work. All work has been completed in accordance with the approved work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lupe Carrasco	Approved by Environmental Specialist:	
Title: Environmental Coordinator	Approval Date: 3/16/2015	Expiration Date: N/A
E-mail Address: gcarrasco@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: March 13, 2015 Phone: 575-748-6940	FINAL	

* Attach Additional Sheets If Necessary

2RP-2519