

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 3/13/2015
NMOCD Artesia

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name:	Canvasback 13 Federal #2H	Facility Type:	Flowline
Surface Owner:	Federal	Mineral Owner:	Federal
		Lease No. (API#)	30-015-40538

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	13	24S	31E	330	North	480	East	Eddy

Latitude N32' 13.476 Longitude W103' 43.375

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	70 bbls	Volume Recovered	25 bbls
Source of Release	4" poly waterline	Date and Hour of Occurrence	8/03/2014 2:30 pm	Date and Hour of Discovery	8/03/2014 2:30 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher – OCD, Jeffrey Robertson – BLM		
By Whom?	Amanda Trujillo	Date and Hour	8/4/2014 6:15 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* A split in the polyline caused the release of produced water. The polyline was fused back together and a vacuum truck dispatched to pick up any standing fluids and dispose of at an NMOCD approved facility.					
Describe Area Affected and Cleanup Action Taken.* The impacted area was approximately 27' x 300' along the road. Concho had the spill site sampled to delineate any possible contamination from the release and presented a remediation work plan to the NMOCD and the BLM for approval prior to any significant remediation work. All work has been completed in accordance to the approved work plan.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Lupe Carrasco		Approved by District Supervisor:			
Title: Environmental Coordinator	Approval Date: 3/16/2015	Expiration Date: N/A			
E-mail Address: gcarrasco@concho.com	Conditions of Approval:			Attached <input type="checkbox"/>	
Date March 13, 2015	Phone: 575-746-2010	FINAL			

* Attach Additional Sheets If Necessary

2RP-2449