

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 8/20/2015
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Burnett Oil Co., Inc.	Contact	Leslie Garvis
Address	801 Cherry Street - Suite 1500, Fort Worth, TX 76102	Telephone No.	817-583-8730
Facility Name	Gissler B 3-1	Facility Type	Tank Battery
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-015-37240

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	11	17S	30E	765	North	1857	East	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil/Produced Water	Volume of Release	31 bbls/30 bbls	Volume Recovered	11 bbls/10 bbls
Source of Release	Separator Screen	Date and Hour of Occurrence	4/9/15	Date and Hour of Discovery	4/9/15 06:30
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jim Amos - BLM & M.Bratcher/H. Patterson - OCD		
By Whom?	Leslie Garvis	Date and Hour	4/9/15 1609		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.*

N/A



Describe Cause of Problem and Remedial Action Taken.*

Screen in separator plugged up and sent oil/water into the vent line. Spill was contained in low lying areas to the South of the pad. Thirty one (31) barrels of oil released with eleven (11) barrels recovered. Thirty (30) barrels of produced water released with ten (10) barrels recovered.

Describe Area Affected and Cleanup Action Taken.*

The total area affected was approx 15'X135' within the pasture surrounding the equipment and flowlines. AH-1 and AH-2 were delineated on 4/16/15 and soil samples taken. Addtl samples taken on AH-3. AH-1 & AH-2 have been excavated to 3' below surface and AH-3 to 2' below surface. Impacted soil hauled to Lea Land Disposal. Impacted soil removed & area remediated to below regulatory levels. Closure Report Attached.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Leslie Garvis	Approved by Environmental Specialist: 	
Title: Regulatory Coordinator	Approval Date: 8/25/2015	Expiration Date: NA
E-mail Address: lgarvis@burnettoil.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 8/20/15	Phone: 817-583-8730	

* Attach Additional Sheets If Necessary

2RP-2954