

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Cimarex Energy	Contact: Christine Alderman
Address: 600 N Marienfeld Ste 600 Midland Tx	Telephone No. 432-853-7059
Facility Name: Parkway State Com 5y	Facility Type: Production

Surface Owner: State	Mineral Owner: State	API No. 30-015-38499
----------------------	----------------------	----------------------

#### LOCATION OF RELEASE

Unit Letter C	Section 15	Township 19S	Range 29E	Feet from the 405	North/South Line N	Feet from the 1980	East/West Line W	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-----------------------	-----------------------	---------------------	----------------

Latitude 32.667114 Longitude -104.064786

#### NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 105bbbls	Volume Recovered: 5bbbls
Source of Release: Tank	Date and Hour of Occurrence 6/14/15 pm	Date and Hour of Discovery 6/14/15pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/ Heather Patterson	
By Whom? Christine Alderman	Date and Hour: 6/15/15 1:20pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Lighting struck a produced water storage tank. The tank was blown out of the containment. The destruction of the tank resulted in the release of approximately 105bbbls of produced water. A vacuum truck was utilized to recover approximately 5bbbls of produced water. Talon/LPE mobilized personnel to conduct an initial site assessment and perform soil sampling within the impacted area.

Describe Area Affected and Cleanup Action Taken.\*

Talon/LPE mobilized personnel to conduct an initial site assessment and perform soil sampling within the impacted area. Upon receipt of analytical results from the soil sampling a work plan was generated and subsequently approved by NMOCD. The remediation took place to the scope laid out in the approved work plan. The area was backfilled and contoured to match the surrounding location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Christine Alderman</u>		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Christine Alderman		Approved by Environmental Specialist:	
Title: EHS- Supervisor		Approval Date: <u>9/28/2015</u>	Expiration Date: <u>N/A</u>
E-mail Address: calderman@cimarex.com		Conditions of Approval:	
Date: <u>9-24-15</u> Phone: 432-853-7059		FINAL Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

2RP-3052