

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW1403048842

OPERATOR

☐ Initial Report ☒ Final Report


Name of Company	Oxy Permian Ltd.	Contact	Dusty Wilson
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5771
Facility Name	State 27 #1 CTB	Facility Type	Gathering
Surface Owner	State	Mineral Owner	API No. 30-015-29374

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	27	24S	29E					Eddy County, NM

Latitude N 32.19473° Longitude W 103.97987°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	122 bbls	Volume Recovered	120 bbls
Source of Release	3 inch poly gas/water line from the facility to the main gas gathering system leaked	Date and Hour of Occurrence	01/06/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD		
By Whom?	Kathy Purvis	Date and Hour	01/09/2014		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A leak in the 3 inch poly gas/water line from the facility to the main gas gathering system caused 122 bbls of produced water to spill onto the ground. 120 bbls of produced water were recovered via vacuum truck and the line was repaired or replaced.					
Describe Area Affected and Cleanup Action Taken.*					
The affected area is approximately 5' x 100'. Remediation was completed in accordance with a remediation plan approved by Mike Bratcher of NMOCD on 03/14/2015.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Dusty Wilson		Approved by Environmental Specialist: <i>MBratcher</i>			
Title: Environmental Advisor		Approval Date: 12/03/2015		Expiration Date: N/A	
E-mail Address: Dusty.Wilson@oxy.com		Conditions of Approval: FINAL		Attached <input type="checkbox"/>	
Date: 11/20/15		Phone: (432) 685-5771			

* Attach Additional Sheets If Necessary

2RP-2172