

District I  
 1625 N. French Dr., Hobbs, NM 88240  
 District II  
 811 S. First St., Artesia, NM 88210  
 District III  
 1000 Rio Brazos Road, Aztec, NM 87410  
 District IV  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy Minerals and Natural Resources  
 Oil Conservation Division  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

nAB1524531624

**OPERATOR**

Initial Report  Final Report

<b>Name of Company</b> Devon Energy Production Company	<b>Contact</b> Brett Fulks EHS Representative
<b>Address</b> 6488 Seven Rivers Hwy Artesia, NM 88210	<b>Telephone No.</b> 575-748-1844
<b>Facility Name</b> North Pure Gold 8 Federal 11	<b>Facility Type</b> Salt Water Disposal

<b>Surface Owner</b> Federal	<b>Mineral Owner</b> Federal	<b>API No</b> 30-015-32619
------------------------------	------------------------------	----------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	8	23S	31E	1400	South	1540	East	Eddy

**Latitude:** 32.31545

**Longitude:** -103.795859

**NATURE OF RELEASE**

<b>Type of Release</b> Produced water release	<b>Volume of Release</b> 20 BBLS	<b>Volume Recovered</b> 18 BBLS
<b>Source of Release</b> hole in high pressure hose on H pump	<b>Date and Hour of Occurrence</b> September 1, 2015 2:40 AM	<b>Date and Hour of Discovery</b> September 1, 2015 2:40 AM
<b>Was Immediate Notice Given?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	<b>If YES, To Whom?</b> BLM; Jim Amos OCD-Mike Bratcher	
<b>By Whom?</b> Assistant Production Foreman; David Simmons	<b>Date and Hour</b> BLM-September 1, 2015 4:40 AM OCD- September 1, 2015 2:10 PM	
<b>Was a Watercourse Reached?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>If YES, Volume Impacting the Watercourse</b> N/A	

**If a Watercourse was Impacted, Describe Fully.\***  
 N/A

**Describe Cause of Problem and Remedial Action Taken.\***  
 Hole in high pressure line on the H pump allowed 20 BBLS of produced water to be released. The power to the H pump and the charge pump was shut off and then the closed the valves upstream and downstream of the release to prevent further release. Line is being repaired.

**Describe Area Affected and Cleanup Action Taken.\***  
 20 BBLS of produced water was released. All of the released fluid remained on location. 18 BBLS of the released fluid was recovered via vacuum truck. Environmental Agency will be contacted for remediation services.  
**Approximately 2' of impacted material inside the fence was hand excavated. The impacted area on the pad was excavated to a depth of 1' BGS and the impacted area off the north edge of the pad was excavated to a depth of 5' BGS. Soil samples were collected to a depth of 10' BGS on the pad. On the north side of the pad soil samples were taken down to a depth of 7' BGS. All impacted soil was transported to a division approved disposal facility and backfilled with fresh soil and seeded. Samples were analyzed by Cardinal Laboratories.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jeanette Barron</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Jeanette Barron	Accepted for Record 12/17/2015	
Title: <b>Field Admin Support</b>	Approved by Environmental Specialist:	MLB
E-mail Address: <b>Jeanette.barron@dvn.com</b>	Approval Date: N/A	Expiration Date: N/A
Date: 12.17.15 Phone: <b>575.748.1813</b>	Conditions of Approval: Contaminant impact remaining in battery area deferred <input type="checkbox"/> Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

to time of facility closure or available access around/under equipment 2RP-3233