

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 3/9/2016
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077	
Facility Name: Loco Hills 33 #6 SWD	Facility Type: SWD Battery	
Surface Owner: Federal	Mineral Owner:	API No. 30-015-37478

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	33	17S	30E	2210'	North	2145'	East	Eddy

Latitude 32.7922202589621 Longitude -103.975401459275

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 2246 bbls PW	Volume Recovered: 2210 bbls PW
Source of Release: Piping	Date and Hour of Occurrence: 2/7/2015 11:30 am	Date and Hour of Discovery: 2/7/2015 8:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher – NMOCD / Jeff Robertson – BLM	
By Whom? Lupe Carrasco	Date and Hour: 2/8/2015 11:12 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

This spill was caused fiberglass piping. Vacuum trucks were dispatched to recover standing fluid and dispose of at an NMOCD approved facility. Fiberglass was replaced with poly piping.

Describe Area Affected and Cleanup Action Taken.*

The release occurred inside a lined facility, however approximately 36 bbls carried over the dike on to the location and into the pasture. The release was addressed per the approved work plan under the guidance on NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 3/11/2016	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: September 1, 2015 Phone: 575-748-6940	FINAL	

* Attach Additional Sheets If Necessary

2RP-2844