

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 7/11/2016

NMOCD Artesia

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: SEABISCUIT FEDERAL Battery	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-41563
------------------------	------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	12	24S	31E	330'	South	2200'	West	Eddy

Latitude/Longitude 32.2255325,-103.732933

**NATURE OF RELEASE**

Type of Release: Oil	Volume of Release: 10 bbls oil	Volume Recovered: 8 bbls oil
Source of Release: Broken sight glass	Date and Hour of Occurrence: 6/26/2016 unknown	Date and Hour of Discovery: 6/26/2016 8:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

This release was caused by a broken sight glass on the heater treater. A vacuum truck was dispatched to recover all the standing fluid and excavate gravel.

Describe Area Affected and Cleanup Action Taken.\*

This release occurred within the lined containment. The impacted gravel was excavated, facility cleaned and put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Amanda T. Davis</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 7/22/2016	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval:  FINAL	Attached <input type="checkbox"/>
Date: July 11, 2016 Phone: 575-748-6940		

\* Attach Additional Sheets If Necessary

2RP-3760