

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JUL 14 2011

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NMLB1122433065

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Cimarex Energy <u>162683</u>	Contact: Ronny Snow
Address: 600 N. Marienfeld St. Midland Tx. 79701	Telephone No. 575-942-8781
Facility Name: Crescent Hale 1 Federal #1	Facility Type: Production

Surface Owner: Unknown	Mineral Owner: BLM	Lease No. API# 30-015-37652
------------------------	--------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section #1	Township 19S	Range 30E	Feet from the 330'	North/South Line North	Feet from the 330'	East/West Line West	County Eddy
-------------	------------	--------------	-----------	--------------------	------------------------	--------------------	---------------------	-------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Water Tank Ran Over	Volume of Release: 100bbbs	Volume Recovered: 100Blls
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? Required <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not	If YES, To Whom? Jim Amos with BLM & Mike Bratcher with OCD	
By Whom? Ronny Snow	Date and Hour : 7/13/11 @ 11:58 (BLM) AM & 3:51 PM (OCD)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Water hauler didn't show up to haul water (Driver Quit), Contacted Crain Hot Oiler & called for trucks & picked up fluid, Note: fluid was contained inside of a lined berm, (20 mill liner)

Describe Area Affected and Cleanup Action Taken.* Inside of lined berm, called for vacuum trucks & picked up fluid.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Ronald G. Snow</u>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Ronald G. Snow	Signed By <u>Mike Bratcher</u>	
Title: Production Foreman	Approval Date: <u>AUG 12 2011</u>	Expiration Date:
E-mail Address: <u>RSnow@cimarex.com</u>	Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	Attached <input type="checkbox"/>
Date: 7/14/11	Phone: 575-942-8781	

* Attach Additional Sheets If Necessary

OR C-141 Final Report
by 9/12/2011

2RP-835