

District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Avenue, Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources
 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-141
 Revised October 10, 2003

Submit 2 Copies to appropriate
 District Office in accordance
 with Rule 116 on back
 side of form

Release Notification and Corrective Action

nHMP1416433238

OPERATOR

Initial Report Final Report



Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street	Telephone No. 575-748-1471	
Facility Name NDDUP #60	API Number 30-015-27053	Facility Type Well Pad
Surface Owner State	Mineral Owner State	Lease No. NM-0557142

LOCATION OF RELEASE

Unit Letter H	Section 19	Township 19S	Range 25E	Feet from the 1980'	North/South Line North	Feet from the 660'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.64817 Longitude 104.51712

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 5 B/PW	Volume Recovered 3 B/PW
Source of Release Water Line	Date and Hour of Occurrence 5/1/2014; PM	Date and Hour of Discovery 5/1/2014; PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* The produced water escaped from a dead line at an abandoned location. Vacuum trucks were called.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 25' X 25'. Vacuum trucks were called to recover the produced water. Impacted soils scraped (taken to an NMOCD approved facility) and micro blazed. Fresh topsoil replaced removed impacted soils. Depth to Ground Water: >100' (approximately 100', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on small amounts of produced water released/amounts recovered and impacted soils removed, Yates Petroleum Corporation requests closure.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Robert Asher	Approved by District Supervisor: 	
Title: NM Environmental Regulatory Supervisor	Approval Date: 6/13/14	Expiration Date: N/A
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: N/A FINAL	Attached <input type="checkbox"/>
Date: Thursday, June 05, 2014 Phone: 575-748-4217	2RP- 2345	

* Attach Additional Sheets If Necessary

2RP-2345

Tanna Adams

From: Tanna Adams
Sent: Thursday, June 05, 2014 4:05 PM
To: Mike Bratcher (mike.bratcher@state.nm.us)
Cc: Bob Asher
Subject: NDDUP #60
Attachments: NNDUP 60.pdf

Tracking:	Recipient	Read
	Mike Bratcher (mike.bratcher@state.nm.us)	
	Bob Asher	Read: 6/5/2014 4:07 PM

Mr. Bratcher,

Please find attached the C141 Initial/Final for the below listed location:

NDDUP #60
30-015-27053
Section 19, T19S-R25E
1980 FNL & 660 FEL
Eddy County, New Mexico

Thank you,

Tanna Adams
Yates Petroleum Corporation
Environmental Tech
Environmental Department
TCAdams@yatespetroleum.com