

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

nAB1612652299

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	OXY USA INC	Contact	CASEY L SUMMERS
Address	PO BOX 4294; HOUSTON, TX 77210	Telephone No.	575-513-8289
Facility Name	GOODNIGHT 27 FEDERAL #1 CTB	Facility Type	CTB
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-015-22157

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	27	23S	29E	660	SOUTH	1980	WEST	EDDY

Latitude\_ 32.27016° \_ Longitude\_ 103.97483° \_ NAD83

### NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	9 bbls	Volume Recovered	0 bbls
Source of Release	Corrosion of a 2" steel water transfer line	Date and Hour of Occurrence	4/22/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM		
By Whom?	Kathy@ BBC International, Inc.	Date and Hour	04/22/2016 @ 2:55 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Corrosion of a 2" steel water transfer line caused 9 bbls of produced water to leak. No fluids were recovered and the line was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 60' x 60' on location east of the tanks. Remediation was completed in accordance with the remediation plan approved for the release (2RP-3672) by Shelly Tucker of the BLM on 8-26-2016 and by Mike Bratcher of the NMOCD on 9-2-2016.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: CASEY L SUMMERS		Approved by Environmental Specialist: 	
Title: ENVIRONMENTAL ADVISOR		Approval Date: 9/14/17	Expiration Date: N/A
E-mail Address: <a href="mailto:casey_summers@oxy.com">casey_summers@oxy.com</a>		Conditions of Approval: Like approval BLM	
Date: 6-20-17 Phone: 575-513-8289		Attached <input type="checkbox"/>	
		FINAL	

\* Attach Additional Sheets If Necessary

2RP-3672