

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Received 10/13/2017
NMOCD Dist 2

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1717157175

OPERATOR

Initial Report Final Report

Name of Company: COG Operating, LLC (OGRID# 229137)	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No.: 432-683-7443
Facility Name: State GQ Com #001 SWD	Facility Type: SWD
Surface Owner: State	Mineral Owner: State
API No.: 30-015-22894	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	7	25S	28E	1980	South	1980	East	Eddy

Latitude: 32.1428375 Longitude: -104.1246643 NAD83

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 45bbbls	Volume Recovered: 44bbbls
Source of Release: Water Tank	Date and Hour of Occurrence: 6/16/2017 12:00am	Date and Hour of Discovery: 6/16/2017 12:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Crystal Weaver-NMOCD Amber Groves-NMSLO	
By Whom? Dakota Neel	Date and Hour: 6/17/2017	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A corroded valve resulted in the release of approximately 45bbbls of produced water. The valve was replaced.		
Describe Area Affected and Cleanup Action Taken.* The release was contained within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. The containment was pressure washed to remove any residue from the release. The lined containment was inspected and found to be structurally sound.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheldon Hitchcock</i>		OIL CONSERVATION DIVISION	
Printed Name: Sheldon L. Hitchcock		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: HSE Coordinator	Approval Date: 10/24/17	Expiration Date: N/A	
E-mail Address: slhitchcock@concho.com	Conditions of Approval: N/A		Attached <input type="checkbox"/>
Date: 10/13/2017	Phone: 575-746-2010		
FINAL			

* Attach Additional Sheets If Necessary

2RP-4257