

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised April 3, 2017

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

nAB1808242167

**OPERATOR**
 Initial Report  Final Report

Name of Company: Marathon Oil Permian LLC	Contact: Callie Karrigan
Address: 2423 Bonita St, Carlsbad, NM 88220	Telephone No. 405-202-1028 (cell) 575-297-0956 (office)
Facility Name: Rock Island 16 State 1H	Facility Type: oil well

Surface Owner	Mineral Owner	API No 30-015-38461
---------------	---------------	---------------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	16	18S	26E	2260	North	2310	East	Lea

Latitude 32.748924 Longitude -104.383218 NAD83

### NATURE OF RELEASE

Type of Release: oil	Volume of Release: 66 bbls	Volume Recovered: 66 bbls
Source of Release: oil tank	Date and Hour of Occurrence 03/06/2018 time unknown	Date and Hour of Discovery 03/06/2018 11:45 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher and Crystal Weaver - email	
By Whom? Callie Karrigan	Date and Hour: 03/06/2018 04:37 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*

At approximately 11:45 am, the site Operator reported standing fluids in lined tank containment due to a suspected tank leak. Approximately 66 barrels of oil was released inside containment and remained onsite. The tank was isolated.

Describe Area Affected and Cleanup Action Taken.\*

A vac truck was immediately dispatched to recover standing fluids. The tank was isolated, emptied and taken out of service. Affected gravel/rock was removed from containment. The liner was assessed, showed no breaches of containment and maintained integrity. The liner was power washed and absorbent material used to recover excess fluids and/or residue. New material was placed in containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Callie Karrigan</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Callie Karrigan		Approved by Environmental Specialist: <i>Mike Bratcher</i>	
Title: HES Professional		Approval Date: 4/26/18	Expiration Date: N/A
E-mail Address: <a href="mailto:cnkarrigan@marathonoil.com">cnkarrigan@marathonoil.com</a>		Conditions of Approval: N/A	
Date: 04/26/2018 Phone: 405-202-1028		<b>FINAL</b>	
		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

2RP-4670