

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Recd:02/05/18

NMOCD Dist 2

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

NAB1711042670

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company	OXY USA WTP LP	Contact	WADE DITTRICH
Address	PO BOX 4294; HOUSTON, TX 77210	Telephone No.	575-390-2828
Facility Name	MCKITTRICK HILLS CTB	Facility Type	CENTRAL TANK BATTERY
Surface Owner	STATE	Mineral Owner	STATE
		API No.	30-015-21010

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	14	22S	24E	2390	NORTH	830	EAST	EDDY

Latitude\_32.3916512\_ Longitude\_-104.4632568\_ NAD83

**NATURE OF RELEASE**

Type of Release	OIL & PRODUCED WATER	Volume of Release	85 bbls OIL - 10 bbls PW	Volume Recovered	80 bbls
Source of Release	WATER TANKS SPILLED OVER	Date and Hour of Occurrence	4-18-2017	Date and Hour of Discovery	4-19-2017
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	MIKE BRATCHER-NMOCD; CRYSTAL WEAVER-NMOCD; SHELLY TUCKER-BLM		
By Whom?	CASEY SUMMERS	Date and Hour	4-19-2017 9:54AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Spill was caused by water tanks spilling over due to the injection pumps not running properly. Pumps and alarm were repaired and check to prevent future release. 80 bbls of free fluid was recovered by vacuum truck.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 80' X 40' on location (measurements are subject to change with future GPS track). Remediation was completed in accordance with a remediation plan approved by the NMOCD (9/20/17 by Mike Bratcher) and BLM (10/3/17 by Shelly Tucker).

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: WADE DITTRICH	Approved by Environmental Specialist: 		
Title: ENVIRONMENTAL SPECIALIST	Approval Date: 07/12/18	Expiration Date: N/A	
E-mail Address: WADE.DITTRICH@OXY.COM	Conditions of Approval: Like approval BLM	Attached <input type="checkbox"/>	
Date: 2-5-18 Phone: 575-390-2828	<b>FINAL</b>		

\* Attach Additional Sheets If Necessary

2RP-4178