

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production Company	Contact Mike Shoemaker
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-748-3371
Facility Name Emerald PWU 20 1H	Facility Type Oil

Surface Owner State	Mineral Owner State	API No 30-015-38338
----------------------------	----------------------------	----------------------------

LOCATION OF RELEASE

Unit Letter D	Section 20	Township 19S	Range 29E	Feet from the 400	North/South Line North	Feet from the 330	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude: 32.6525154

Longitude: -104.1045456

NATURE OF RELEASE

Type of Release Produced Water & Oil	Volume of Release 38bbbls produced water / 2bbbls oil	Volume Recovered 14bbbls produced water / 1bbl oil
Source of Release Three Phase Separator	Date and Hour of Occurrence January 30, 2017 @ 1:30 AM	Date and Hour of Discovery January 30, 2017 @ 1:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, OCD Shelly Tucker, BLM	
By Whom? Hub Perry, Production Foreman	Date and Hour Mike Bratcher, OCD January 30, 2017 2:10 PM Shelly Tucker, BLM January 30, 2017 2:23 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Water dump cracked due to sand wash out on the 3-phase separator. The well was shut in at the well head to stop the release. Repairs have been made and the separator is back in service.

Describe Area Affected and Cleanup Action Taken.*
Approximately 38bbbls produced water and 2bbl oil was released on location in approximately a 35' wide by 50' long area. A vacuum truck was contacted and recovered 14bbbls produced water and 1bbl oil from location. Upon approval of the remediation work plan Talon/LPE conducted the remediation in accordance with the approved work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Michael Shoemaker</i>	OIL CONSERVATION DIVISION	
Printed Name: Michael Shoemaker	Approved by Environmental Specialist: 	
Title: Environmental Specialist	Approval Date: 08/20/18	Expiration Date: N/A
E-mail Address: mike.shoemaker@dvn.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 08/16/18 Phone: 575.748.3371	N/A	

* Attach Additional Sheets If Necessary

FINAL 2RP-4109