

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised April 3, 2017

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Devon Energy Production Company	Contact Michael Shoemaker
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-748-3371
Facility Name Doc Holliday 32 State Com 1	Facility Type Oil

Surface Owner Federal	Mineral Owner State	API No. 30-015-41145
-----------------------	---------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	32	24S	27E					Eddy

Latitude\_32.18022\_ Longitude\_-104.21954\_ NAD83

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release Unknown	Volume Recovered 0bbls
Source of Release Illegal Dumping	Date and Hour of Occurrence December 3, 2017 @5:30 PM MST	Date and Hour of Discovery December 3, 2017 @ 5:30 PM MST
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelly Tucker, BLM Mike Bratcher & Crystal Weaver, OCD	
By Whom? Mike Shoemaker, EHS Professional	Date and Hour December 4, 2017 @ 8:56 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
Local rancher contacted Devon staff and reporting suspicious activity that appeared to be an illegal dumping event. Devon staff went to the location and confirmed that an illegal dumping event had occurred. There was evidence of released fluids and impacted soils and truck tracks that were observed at the location.

Describe Area Affected and Cleanup Action Taken.\*  
The pad surface and pasture were affected in an approximate 15'x90' area. The impacted soil was excavated and the resulting confirmation samples indicated TPH to be below NMOCD RRAL's.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Michael Shoemaker</i>	<b><u>OIL CONSERVATION DIVISION</u></b>	
	Approved by Environmental Specialist: 	
Printed Name: Michael Shoemaker	Approval Date: 08/20/18	Expiration Date: N/A
Title: Environmental Professional	Conditions of Approval:	
E-mail Address: mike.shoemaekr@dvn.com	Like Approval BLM	Attached <input type="checkbox"/>
Date: 08/16/18 Phone: 575.748.3371		

\* Attach Additional Sheets If Necessary

**FINAL 2RP-4547**