

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

OCD Rec'd:12/13/17

Form C-141  
Revised April 3, 2017

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company: XTO Energy	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No: 432-661-0571
Facility Name: Coral Canyon Federal Central Tank Battery (API: Coral Canyon Federal #4H)	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-42923
------------------------	------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter S	Section 5	Township 25S	Range 29E	Feet from the 47	North/South Line South	Feet from the 156	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	---------------------	---------------------------	----------------------	------------------------	----------------

Latitude \_32.152504\_ Longitude \_-103.998535\_ NAD83

**NATURE OF RELEASE**



Type of Release Oil and produced water	Volume of Release 0.69 BO 12.91 BPW	Volume Recovered 0.45 BO 1.05 BPW
Source of Release Header	Date and Hour of Occurrence 4/12/2017 time unknown	Date and Hour of Discovery 4/12/2017 6:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
Equipment failure at 8" victaulic header. Header was repaired.

Describe Area Affected and Cleanup Action Taken.\*  
Fluid spilled in a narrow winding path downhill to the southwest approximately 480'. Free standing fluids were recovered. Remediation crew addressed the spill area per a NMOCD and BLM approved work plan. Remediation contractor collected a series of confirmatory samples. The excavated areas were backfilled to grade with clean, compacted caliche from a nearby source. All impacted soils were disposed of at a NMOCD approved facility. Silt fencing and hay bales were deployed as a measure to minimize the potential for erosion at the site.  
This is the closure report for 2RP-4190

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amy Ruth		Approved by Environmental Specialist: 	
Title: Environmental Coordinator		Approval Date: 08/20/18	Expiration Date: N/A
E-mail Address: Amy_Ruth@xtoenergy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 12/12/2017 Phone: 432-661-0571	Like Approval BLM		2RP-4190

\* Attach Additional Sheets If Necessary

A#: pAB1711751353