

Hamlet, Robert, EMNRD

From: Hamlet, Robert, EMNRD
Sent: Thursday, June 27, 2019 9:33 AM
To: 'Andresen, Rebecca'
Cc: Bratcher, Mike, EMNRD; Venegas, Victoria, EMNRD; Michelson, Jason C
Subject: RE: Amoco Federal 11-1, Inspection No. iTM1734133661

Rebecca,

Sounds like this one is already being addressed. Many of these inspection letters are very similar.

The OCD understands that you are currently evaluating these wells for ongoing production. We can give you a 12 month extension if the wells will be plugged and addressed by then. Otherwise, please remove the stained soil and replace with clean soil. Take a picture after the stained soil has been replaced with clean soil. Send in a letter and picture for each well in the "Inspection Detail Section" explaining that the violation has been addressed and we will administrate the violation has been taken care.

Please, equip the Amoco Federal 11 #1 tank battery location with a placard if not completed. The Windsock is usually a safety feature provided to the pumpers by the operator, not necessarily an OCD directive.

Please let us know your decision on "staining" clean-up.

Thank you,

Robert J Hamlet
State of New Mexico
Energy, Minerals, and Natural Resources
Oil Conservation Division
811 S. First St., Artesia NM 88210
(575) 840-5963
Robert.Hamlet@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

From: Andresen, Rebecca <Rebecca.Andresen@arcadis.com>
Sent: Thursday, June 13, 2019 12:20 PM
To: Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>
Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>; Michelson, Jason C <JMichelson@chevron.com>
Subject: [EXT] Amoco Federal 11-1, Inspection No. iTM1734133661

Mr. Hamlet,

Please find attached a Site Status letter regarding inspection number iTM1734133661, conducted in 2017. This inspection identified a staining violation. Chevron acquired the lease for this well in October 2018 and is currently evaluating this well for ongoing production. The attached letter proposes that work to address the violation will be conducted in conjunction with maintenance activities at this well.

Please let us know if you have questions.

Best Regards,

Rebecca Andresen, P.G. | Vice President | rebecca.andresen@arcadis.com
Arcadis | 1100 Olive Way, Suite 800, Seattle, WA | 98101 | USA
T. +1 206 726 4717 | M. +1 206 295 3273

Professional Registration / WA-2588 | GA-1589 | TN-4728

Connect with us! www.arcadis.com | [LinkedIn](#) | [Twitter](#) | [Facebook](#)



This email and any files transmitted with it are the property of Arcadis and its affiliates. All rights, including without limitation copyright, are reserved. This email contains information that may be confidential and may also be privileged. It is for the exclusive use of the intended recipient(s). If you are not an intended recipient, please note that any form of distribution, copying or use of this communication or the information in it is strictly prohibited and may be unlawful. If you have received this communication in error, please return it to the sender and then delete the email and destroy any copies of it. While reasonable precautions have been taken to ensure that no software or viruses are present in our emails, we cannot guarantee that this email or any attachment is virus free or has not been intercepted or changed. Any opinions or other information in this email that do not relate to the official business of Arcadis are neither given nor endorsed by it.