

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Incident ID	NAB1928842829
District RP	2RP-5667
Facility ID	
Application ID	pAB1928839220

## Release Notification

IFMBA-190930-C-1410

### Responsible Party

Responsible Party	XTO Energy	OGRID	5380
Contact Name	Kyle Littrell	Contact Telephone	432-221-7331
Contact email	Kyle_Littrell@xtoenergy.com	Incident # (assigned by OCD)	NAB1928842829
Contact mailing address	522 W. Mermod, Carlsbad, NM 88220		

### Location of Release Source

Latitude 32.019293 Longitude -103.944616  
(NAD 83 in decimal degrees to 5 decimal places)

Site Name	Ross Draw 25-36 Federal 161H	Site Type	Well
Date Release Discovered	09/15/2019	API# (if applicable)	30-015-45591 (Ross Draw 25 36 Fed Com #161H)

Unit Letter	Section	Township	Range	County
D	25	26S	29E	EDDY

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: \_\_\_\_\_)

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input checked="" type="checkbox"/> Other (describe) Treated water	Volume/Weight Released (provide units) 50 bbls and 20 gals	Volume/Weight Recovered (provide units) 50 bbls

Cause of Release: Frac tank overflowed due to valve being open on manifold. 50 bbls of treated water was recovered from containment and returned to tank. Additional third party resources have been retained to assist in the remediation.


State of New Mexico  
Oil Conservation Division

Incident ID	NAB1928842829
District RP	2RP-5667
Facility ID	
Application ID	pAB1928839220

Was this a major release as defined by 19.15.29.7(A) NMAC?  <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?  An unauthorized release of a volume of 25 barrels or more
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Notice provided by Kyle Littrell to Mike Bratcher, Rob Hamlet, Victoria Venegas, and Jim Griswold (NMOCD), and Jim Amos and Deborah McKinney (BLM) on 9/16/19 by email.	

### Initial Response

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:  N/A	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Kyle Littrell</u>	Title: <u>SH&amp;E Supervisor</u>
Signature: 	Date: <u>9/30/19</u>
email: <u>Kyle_Littrell@xtoenergy.com</u>	Telephone: _____
<b><u>OCD Only</u></b>	
Received by: <u>Amalia Bustamante</u>	Date: <u>10/15/2019</u>