

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nMLB 1/22854480

277558

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company : LIME ROCK RESOURCES II-A, L.P	Contact : Jerry Smith	
Address : 1111 Bagby Street Suite 4600, Houston ,TX 77002	Telephone No. : 575-748-9724	
Facility Name : Condor 8 Federal #001H	Facility Type: Battery	
Surface Owner : Federal	Mineral Owner	Lease No. : API #30-015-35829

LOCATION OF RELEASE

Unit Letter F	Section 8	Township 18S	Range 27E	Feet from the 1770	North/South Line FNL	Feet from the 2525	East/West Line FWL	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	-------------

Latitude 32.76464 Longitude -104.300765

NATURE OF RELEASE

Type of Release : OIL	Volume of Release : 15 bbls	Volume Recovered: -0-
Source of Release : Overflow Oil Transport	Date and Hour of Occurrence: 7/28/11 10:07 am	Date and Hour of Discovery: 7/28/11 10:07 am
Was Immediate Notice Given? ☐ Yes ☐ No ☒ Not Required	If YES, To Whom?	
By Whom? Transport Driver	Date and Hour : 7/28/11 10:07 am	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

During loading procedures the driver for Great Lakes Transport overflowed his transport truck.

RECEIVED


AUG 1 2011

Describe Area Affected and Cleanup Action Taken.*

The affected area was located on the well location south of the battery. This area was measured to be approximately 72' long x 122' wide. A small area located south of the well location was affected by a minor flow path. Due to rock and boulders off the edge of location, this area was not able to be measured. Great Lakes Transport was contacted; they will provide equipment for the excavation of release. Talon/LPE was also contacted for the correction of the release.

NMOCD ARTESIA

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jerry Smith	Signed By  Approved by District Supervisor:	
Title: Assistant Production Supervisor	Approval Date: AUG 16 2011	Expiration Date:
E-mail Address: jsmith@limerockresources.com	Conditions of Approval:	Attached ☐
Date: 8/01/11 Phone: 575-748-9724	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 9/16/2011	

* Attach Additional Sheets If Necessary

2RP-853