

RECEIVED

APR 21 2020

EMNRD-OCDARTESIA

RECEIVED

Submit One Copy To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S First St., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Minerals and Natural Resources

Form C-103
Revised November 3, 2011

EMNRD-OCDARTESIA

CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-10736
5. Indicate Type of Lease STATE [X] FEE []
6. State Oil & Gas Lease No. E-2211
7. Lease Name or Unit Agreement Name STATE
8. Well Number 2
9. OGRID Number 025542
10. Pool name or Wildcat N. BENSON (QUEEN-GRAYBURG)
SUNDRY NOTICES AND REPORTS ON WELLS
1. Type of Well: [X] Oil Well [] Gas Well [] Other
2. Name of Operator YATES ENERGY CORPORATION
3. Address of Operator PO BOX 2323, ROSWELL, NM 88202
4. Well Location Unit Letter B : 2,310 feet from the E line and 330 feet from the N line
Section 32 Township 18S Range 30E NMPM County EDDY
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,431' GR
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK [] PLUG AND ABANDON []
TEMPORARILY ABANDON [] CHANGE PLANS []
PULL OR ALTER CASING [] MULTIPLE COMPL []
SUBSEQUENT REPORT OF:
REMEDIAL WORK [] ALTERING CASING []
COMMENCE DRILLING OPNS [] P AND A []
CASING/CEMENT JOB []
OTHER: [] [X] Location is ready for OCD inspection after P&A
[X] All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
[X] Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
[X] A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.

- [X] The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. Power Lines/Poles not removed Buried power lines not removed
[X] Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
[X] All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) Trash on location and on road to location not removed
[X] All other environmental concerns have been addressed as per OCD rules.
[X] Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines. Hardtop must be plowed up

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE [Signature] TITLE ENGINEERING CONSULTANT DATE 04/14/2020
TYPE OR PRINT NAME MICHAEL STEWART E-MAIL: mstewart@helmsoil.com PHONE: (432)682-1122
For State Use Only

APPROVED BY: [Signature] DENIED DATE gc 4/24/2020