<b>D</b>			Rec'd	05/11/2020	) - NMOCD	
Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR				FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018		
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					5. Lease Serial No. NMNM17056	
					6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well □ Gas Well □ Other					8. Well Name and No. NASH UNIT 203H	
2. Name of Operator XTO ENERGY INCORPORATED Contact: TRACIE J CHERRY					9. API Well No. 30-015-45496-00-X1	
3a. Address 6401 HOLIDAY HILL ROAD E MIDLAND, TX 79707	. (include area code) 10. Field and Pool FORTY NIN			Exploratory Area RIDGE-BONE SPRING		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, State		
Sec 19 T23S R30E NWNE 61 32.296047 N Lat, 103.918465		EDDY COUNTY, NM				
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA
TYPE OF SUBMISSION		TYPE OF ACTION				
□ Notice of Intent	□ Acidize	🗖 Dee	pen	Product	ion (Start/Resume)	□ Water Shut-Off
—	□ Alter Casing	-	Iraulic Fracturing	□ Reclam		U Well Integrity
Subsequent Report	Casing Repair	_			olete	Other Drilling Operations
☐ Final Abandonment Notice	□ Change Plans □ Convert to Injection		g and Abandon g Back	□ Tempor □ Water I	arily Abandon Disposal	
If the proposal is to deepen direction. Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f XTO Energy respectfully subn well. **RE-FILED PER NMOCD RE 01/11/19 Spud 24" hole. SD drilling @ 7	rk will be performed or provide l operations. If the operation re bandonment Notices must be fil inal inspection. nits this sundry notice to r EQUEST. REVISED TO C	the Bond No. o sults in a multip ed only after all report drilling	n file with BLM/BIA le completion or reco requirements, includ operations on the	. Required sui mpletion in a ling reclamation e referenced	bsequent reports must be new interval, a Form 316 n, have been completed a	filed within 30 days 0-4 must be filed once and the operator has
01/16/19 - 01/17/19 Continue drilling 24" hole. TD	hole @ 388'					
01/18/19 Accep[ted 05/11/2020 - KMS NMOCD						
14. I hereby certify that the foregoing is	Electronic Submission #	GY INCORPO	RATED, sent to th	e Carlsbad	-	
Name(Printed/Typed) TRACIE J CHERRY			Title REGULATORY ANALYST			
Signature (Electronic Submission)			Date 05/07/2020			
	THIS SPACE FO		L OR STATE	OFFICE U	SE	
Approved By_ACCEPTED			JONATHON SHEPARD TitlePETROLEUM ENGINEER Date 05/08/2020			
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Carlsbad			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent				willfully to m	ake to any department or	agency of the United
(Instructions on page 2) ** BLM REV	ISED ** BLM REVISEI	D ** BLM R	EVISED ** BLN		D ** BLM REVISE	D **

## Additional data for EC transaction #514444 that would not fit on the form

## 32. Additional remarks, continued

Run 18-5/8", 87.5# J55 csg to 388'. Cement using 1180 sxs (266 bbls) Class C cmt. Bump plug. Return 438 sxs (106 bbls) cmt to surface. WOC

01/20/19

Test BOP 250 low/1500 high for 30 min. (good). Drill shoe track. Drill 17-1/2" hole.

01/22/19

TD hole @ 3229'. Run 13-3/8", 68#, HCL80 csg to 3229'. LEAD CMT: 1745 sxs (603 bbls) Econocem HCL C cmt. TAIL CMT: 750 sxs (180 bbls) Halcem-C. Bump plug. Return 579 sxs to surface. WOC.

01/24/19 Test BOP 250 low/5000 high

01/25/19 - 01/26/19 Test csg to 1500 psi (good). Drill shoe track. Perform FIT. Drill 12-1/4" hole.

01/26/19 - 01/29/19 SD for rig repair.

02/01/19 - 02/02/19

TD hole @ 7312'. Run 9-5/8" 40# J55 csg to 7302', DV tool @ 3304'. 1ST STAGE LEAD: 900 sxs (342 bbls) Neocem. 1ST STAGE TAIL: 495 sxs (118 bbls) Halcem. Bump plug. Open DV tool. Return cmt to surface. 2ND STAGE LEAD: 665 sxs (227 bbls) Econocem 2NS STAGE TAIL: 80 sxs (22 bbls) Halcem. Bump plug. Close DV tool. Return 30 bbls cmt to surface. WOC.

(Continued on attachment)

## Revisions to Operator-Submitted EC Data for Sundry Notice #514444

	Operator Submitted	BLM Revised (AFMSS)
Sundry Type:	DRG SR	DRG SR
Lease:	NMNM17056	NMNM17056
Agreement:		
Operator:	XTO ENERGY INC 6401 HOLIDAY HILL RD BLDG 5 MIDLAND, TX 79707 Ph: 432-221-7379	XTO ENERGY INCORPORATED 6401 HOLIDAY HILL ROAD BLDG 5 MIDLAND, TX 79707 Ph: 432.683 2277
Admin Contact:	TRACIE J CHERRY REGULATORY COORDINATOR E-Mail: tracie_cherry@xtoenergy.com	TRACIE J CHERRY REGULATORY ANALYST
	Ph: 432-221-7379	Ph: 432.221.7379
Tech Contact:	TRACIE J CHERRY REGULATORY COORDINATOR E-Mail: tracie_cherry@xtoenergy.com	TRACIE J CHERRY REGULATORY ANALYST
	Ph: 432-221-7379	Ph: 432.221.7379
Location: State: County:	NM EDDY	NM EDDY
Field/Pool:	FORTY NINER RIDGE;B.S.,W	FORTY NINER RIDGE-BONE SPRING
Well/Facility:	NASH UNIT 203H Sec 19 T23S R30E Mer NMP NWNE 610FNL 1905FEL	NASH UNIT 203H Sec 19 T23S R30E NWNE 610FNL 1905FEL 32.296047 N Lat, 103.918465 W Lon