Submit One Copy To Appropriate District Office	State of New Mexico		EMNRD-OCD ARTESIA REC'D: 6/12/2020 Form C-103 Revised November 3, 2011		
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II	Energy, Minerals and Natural Resources		WELL API NO. 30-015-24323		
811 S. First St., Artesia, NM 88210 District III			5. Indicate Type	e of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505		STATE 6. State Oil & O	FEE S	
1220 S. St. Francis Dr., Santa Fe, NM			6. State Off & C	ias Lease No.	
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name	or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Jackson Estate E	Jackson Estate BY	
PROPOSALS.)			8. Well Number	8. Well Number	
1. Type of Well: ☑Oil Well ☐ Gas Well ☐ Other 2. Name of Operator				9. OGRID Number	
EOG Resources, Inc.			7377	7377	
3. Address of Operator			10. Pool name or Wildcat		
105 South Fourth Street, Artesia, NM 88210 4. Well Location			Eagle Creek; San Andres		
Unit Letter E: 2310 feet from the North line and 330 feet from the West line					
Section 22	<u> </u>	ange $\frac{-55}{25E}$		ddy County	
11	Elevation (Show whether DR 3541		tc.)		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK PL	UG AND ABANDON	REMEDIAL WO	ORK 🗆	ALTERING CASING	
	HANGE PLANS ☐ JLTIPLE COMPL ☐	COMMENCE D	RILLING OPNS.	P AND A	
FULL OR ALTER CASING MC	THE COMPL	CASING/CEIVIE	INT JOB		
OTHER: Description Descri					
 ✓ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. ✓ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. ✓ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the 					
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR					
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR					
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.					
☐ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and					
other production equipment. Power Lines/Poles removed.					
 ✓ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. ✓ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with 					
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed					
from lease and well location. Casing cut 3' BGL. Casing cut 3' BGL (see attached photos). All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have					
to be removed.)					
All other environmental concerns have been addressed as per OCD rules.					
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines. No, active pipeline(s) within EOG Resources gas/water system.					
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well					
location, except for utility's distribution is	nfrastructure.	_			
When all work has been completed, return this form to the appropriate District office to schedule an inspection.					
\bigcirc \bigcirc \bigcirc			•		
SIGNATURE	IIILE: _	Environmental S	Supervisor	DATE6/1/2020	
TYPE OR PRINT NAME: Robert Ashe	r E-MAIL:	Robert Asher	@eogresources.com	PHONE: <u>575-748-4217</u>	
For State Use Only					
APPROVED BY:	TITLE	Staff 1	Manager	DATE 6/23/2020	
Conditions of Approval (if any):	Entard VM	S NMOCD	J		