EMNRD-OCD ARTESIA Submit One Copy To Appropriate District State of New Mexico Form C-103 REC'D: 7/08/2020 Office Revised November 3, 2011 Energy, Minerals and Natural Resources District I WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 30-015-32351 District II OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III STATE X FEE 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S. St. Francis Dr., Santa Fe, NM KD 3403-000 LO 16490005 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CARLSBAD SOUTH 27 STATE COM DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number 7 1. Type of Well: ☐ Oil Well ☐ Gas Well ☒ Other 2. Name of Operator 9. OGRID Number MARATHON OIL PERMIAN, LLC 372098 3. Address of Operator 10. Pool name or Wildcat 5555 SAN FELIPE ST, HOUSTON, TX 77056 CARLSBAD S MORROW 4. Well Location : 1310 feet from the S line and 660 feet from the W line Unit Letter Township 23S Range 26E County EDDY NMPM Section 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3320' GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK □ PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.□ P AND A П PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB OTHER: П □ Location is ready for OCD inspection after P&A All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and Trash has been removed. Please see attached pictures. other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) All other environmental concerns have been addressed as per OCD rules.

When all work has been completed, return this form to the appropriate District office to schedule an inspection. TITLE REGULATORY PROFESSIONAL DATE 7/8/2020 SIGNATURE E-MAIL: acovarrubias@marathonoil.com TYPE OR PRINT NAME Adrian Covarrubias PHONE: 713-296-3368

Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-

| If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well

For State Use Only

retrieved flow lines and pipelines.

location, except for utility's distribution infrastructure.

Staff Manager APPROVED BY: TITLE DATE 7/14/2020