

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.5. Lease Serial No.
NMNM107368

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
PEACHES 19 FEDERAL 1H9. API Well No.
30-015-40250-00-S110. Field and Pool or Exploratory Area
COTTONWOOD DRAW-BONE SPRING

11. County or Parish, State

EDDY COUNTY, NM

SUBMIT IN TRIPLICATE - Other instructions on page 2

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

CHEVRON USA INCORPORATED

Contact: CINDY H MURILLO

E-Mail: CERRERAMURILLO@CHEVRON.COM

3a. Address

6301 DEAUVILLE BLVD
MIDLAND, TX 79706

3b. Phone No. (include area code)

Ph: 575.263.0431
Fx: 575.263.0445

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 19 T25S R27E NWNE 330FNL 2310FEL
32.121769 N Lat, 104.228332 W Lon

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input checked="" type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomplate in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

CHEVRON USA INC IS REQUESTING FOR THE ABOVE WELL TO RETURN TO PRODUCTION. THE WELL HAS RETURNED TO PRODUCTION ON JUNE 21,2020. THE WELL HAS MADE 84- OIL, 788- GAS, AND 0- WATER.

Accepted - KMS NMOCD

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #534214 verified by the BLM Well Information System
For CHEVRON USA INCORPORATED, sent to the Carlsbad
Committed to AFMSS for processing by PRISCILLA PEREZ on 10/20/2020 (21PP0253SE)

Name (Printed/Typed) CINDY H MURILLO

Title PERMITTING SPECIALIST

Signature (Electronic Submission)

Date 10/15/2020

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By

ACCEPTEDJONATHON SHEPARD
Title PETROLEUM ENGINEER

Date 11/20/2020

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office Carlsbad

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

Revisions to Operator-Submitted EC Data for Sundry Notice #534214

	Operator Submitted	BLM Revised (AFMSS)
Sundry Type:	RESUME SR	RESUME SR
Lease:	NMNM107368	NMNM107368
Agreement:		
Operator:	CHEVRON USA INC 6301 DEAUVILLE BLVD MIDLAND, TX 79706 Ph: 575-263-0431	CHEVRON USA INCORPORATED 6301 DEAUVILLE BLVD MIDLAND, TX 79706 Ph: 432 687 7100
Admin Contact:	CINDY H MURILLO LEAD HSE REGULATORY AFFAIRS CO E-Mail: CERRERAMURILLO@CHEVRON.COM Ph: 575-263-0431 Fx: 575-726-3044	CINDY H MURILLO PERMITTING SPECIALIST E-Mail: CERRERAMURILLO@CHEVRON.COM Ph: 575.263.0431 Fx: 575.263.0445
Tech Contact:	CINDY H MURILLO LEAD HSE REGULATORY AFFAIRS CO E-Mail: CERRERAMURILLO@CHEVRON.COM Ph: 575-263-0431 Fx: 575-726-3044	CINDY H MURILLO PERMITTING SPECIALIST E-Mail: CERRERAMURILLO@CHEVRON.COM Ph: 575.263.0431 Fx: 575.263.0445
Location:		
State:	NM	NM
County:	EDDY	EDDY
Field/Pool:	COTTONWOOD DRAW;BONE SPRI	COTTONWOOD DRAW-BONE SPRING
Well/Facility:	PEACHES 19 FEDERAL 1H Sec 19 T25S R27E NWNE 330FNL 2310FEL	PEACHES 19 FEDERAL 1H Sec 19 T25S R27E NWNE 330FNL 2310FEL 32.121769 N Lat, 104.228332 W Lon