

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENTFORM APPROVED  
OMB NO. 1004-0137  
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**  
**Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.**5. Lease Serial No.  
NMNM109756

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

**SUBMIT IN TRIPLICATE - Other instructions on page 2**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

8. Well Name and No.

PEACHES 19 FEDERAL 4H

2. Name of Operator

CHEVRON USA INCORPORATED

Contact: CINDY H MURILLO

E-Mail: CERRERAMURILLO@CHEVRON.COM

9. API Well No.

30-015-42030-00-S1

3a. Address

6301 DEAUVILLE BLVD  
MIDLAND, TX 79706

3b. Phone No. (include area code)

Ph: 575.263.0431  
Fx: 575.263.0445

10. Field and Pool or Exploratory Area

COTTONWOOD DRAW  
UNKNOWN

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 19 T25S R27E Lot 1 150FNL 660FWL  
32.122100 N Lat, 104.235336 W Lon

11. County or Parish, State

EDDY COUNTY, NM

## 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input checked="" type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

CHEVRON USA INC IS REQUESTING FOR THE ABOVE WELL TO RETURN TO PRODUCTION. THE WELL HAS RETURNED TO PRODUCTION ON JUNE10, 2020. THE WELL HAS MADE 0- OIL, 80- GAS, AND 0- WATER.

Accepted - KMS NMOCD

14. I hereby certify that the foregoing is true and correct.

**Electronic Submission #534217 verified by the BLM Well Information System**  
**For CHEVRON USA INCORPORATED, sent to the Carlsbad**  
**Committed to AFMSS for processing by PRISCILLA PEREZ on 10/20/2020 (21PP0254SE)**

Name (Printed/Typed) CINDY H MURILLO

Title PERMITTING SPECIALIST

Signature (Electronic Submission)

Date 10/15/2020

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved By

**ACCEPTED**JONATHON SHEPARD  
Title PETROLEUM ENGINEER

Date 11/20/2020

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office Carlsbad

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\***

## Revisions to Operator-Submitted EC Data for Sundry Notice #534217

	Operator Submitted	BLM Revised (AFMSS)
Sundry Type:	RESUME SR	RESUME SR
Lease:	NMNM109756	NMNM109756
Agreement:		
Operator:	CHEVRON USA INC 6301 DEAUVILLE BLVD MIDLAND, TX 79706 Ph: 575-263-0431	CHEVRON USA INCORPORATED 6301 DEAUVILLE BLVD MIDLAND, TX 79706 Ph: 432 687 7100
Admin Contact:	CINDY H MURILLO LEAD HSE REGULATORY AFFAIRS CO E-Mail: CERRERAMURILLO@CHEVRON.COM  Ph: 575-263-0431 Fx: 575-726-3044	CINDY H MURILLO PERMITTING SPECIALIST E-Mail: CERRERAMURILLO@CHEVRON.COM  Ph: 575.263.0431 Fx: 575.263.0445
Tech Contact:	CINDY H MURILLO LEAD HSE REGULATORY AFFAIRS CO E-Mail: CERRERAMURILLO@CHEVRON.COM  Ph: 575-263-0431 Fx: 575-726-3044	CINDY H MURILLO PERMITTING SPECIALIST E-Mail: CERRERAMURILLO@CHEVRON.COM  Ph: 575.263.0431 Fx: 575.263.0445
Location:		
State:	NM	NM
County:	EDDY	EDDY
Field/Pool:	COTTONWOOD DRAW;BONE SPRI	COTTONWOOD DRAW UNKNOWN
Well/Facility:	PEACHES 19 FEDERAL 4H Sec 19 T25S R27E SWSW 150FNL 660FWL	PEACHES 19 FEDERAL 4H Sec 19 T25S R27E Lot 1 150FNL 660FWL 32.122100 N Lat, 104.235336 W Lon